# MUN Evaluation in Ag Drains Summary to Date

### Sacramento Valley Archetypes

Colusa, Live Oak, Willows, Biggs Sampling period: April – June 2012 Quarterly Review in July 2012




### **Outline**

- Surveys/Meetings with Irrigation/Reclamation Districts
- CV-SALTS Technical Advisory
   Committee Recommendations
- Monitoring Parameters
- Lab Results
- Next Monitoring Events

### Feb/March 2012 - Local Meetings

#### Representatives from:

- Biggs-West Gridley Water District
- Sutter Extension Water District
- Colusa Basin Drainage District
- Glenn-Colusa Irrigation District
- Reclamation District 777
- Reclamation District 833
- Glenn County Board of Supervisors
- Glenn County Dept. of Agriculture
- City of Biggs POTW
- City of Colusa POTW
- City of Live Oak POTW
- City of Willows POTW
- Sacramento Valley Coalition
- California Rice Commission



# Site Surveys - Summary

- No indication of existing MUN use
- Areas are dominated by agriculture much of it rice production
- Water bodies primarily constructed Ag. drains and channels
- Many potential diversions and reuse of water
- District maps were reviewed and used during the surveys

# Site Surveys

### West Side – Colusa Basin Drain

#### Colusa Area – March 6, 2012

- Two potential diversions from Colusa Basin Drain into Powell Slough upstream of effluent discharge
- New Ag. ditch upstream of effluent

#### Willows Area – March 6 & March 14, 2012

Ag. Drain C goes through Sacramento Wildlife Refuge

# Site Surveys (cont.)

### East Side – Sutter Bypass

#### Live Oak Area – March 15, 2012

- During non-irrigation season, water in Lateral 1 is dominated by effluent
- Groundwater seepage another source of water (Butte Sink)

### Biggs Area – March 21, 2012

 Water from the Cherokee Canal is diverted to Duck Clubs in the Butte Creek area

# CV-SALTS TAC (3/9/2012) Recommendations

- In general, monitoring approach and questions approved
- Better to monitor for more parameters than less for the first three months
- Critical review of monitoring plan after first 3 months
  - Review constituents, frequency, period of monitoring, sites
- Have subsequent reviews every 3 months
- Flow data not worth expense
  - Photos; temperature sensors; some instantaneous

7

# CV-SALTS TAC (3/9/2012) Policy Issues

- Initiate efforts on developing a "decision tree"
  - If/when/what monitoring is needed
- Definition of "sustained yield" for surface water
  - Comparison of DPH recommendation vs. Drinking Water Policy
- Determining "baseline" for highly modified systems
- Determine how much "weight" local grower opinions should have in decision process


### Reasonable Potential Analysis

- Parameters with reasonable potential to increase concentration over criteria
  - ◆ Colusa
    - —Nitrate+Nitrite as Nitrogen, Aluminum
  - Live Oak
    - —Nitrate+Nitrite as Nitrogen, Arsenic, Manganese, Iron, Aluminum
  - Willows
    - —Nitrate+Nitrite as Nitrogen, total trihalomethanes
  - Biggs
    - —Electrical conductivity
- Total Dissolved Solids is expected to be directly related to Electrical Conductivity (Colusa NPDES Permit)

# **April-June 2012 Monitoring Parameters**

- 1/month (key constituents):
  - ◆ Volatile Organic Compounds, MBAs, Nitrate as Nitrogen, Nitrite as Nitrogen, boron, sodium, total: aluminum, arsenic, iron, manganese
- 2/month:
  - Specific conductivity, turbidity, pH, dissolved oxygen, temperature

#### MUN Beneficial Use Study - Site Map




# **Monitoring Sites**

Study Area	# of Sites	Cost (\$) for April – June 2012
Biggs	7	\$2,798
Colusa	9	\$3,705
Live Oak	6	\$2,535
Willows	8	\$3,315
TOTAL	30	\$12,353

# West Side - Colusa Basin Drain Specific Conductivity




# **East Side - Sutter Bypass Specific Conductivity**




**Sites - Upstream to Downstream** 

# West Side - Colusa Basin Drain Nitrate as Nitrogen



# East Side - Sutter Bypass Nitrate as Nitrogen



### **Results: Field Measurements**

- Turbidity >5 NTU (2<sup>nd</sup> MCL) at most sites
  - Turbidity < 5 NTU at Butte Creek, Lateral #2 DS & US, Effluent for Colusa, Live Oak, and Willows
- Most sites had pH values within 6.5 8.5 (2<sup>nd</sup> MCL and Basin Plan Objective) except C Main Drain [8.56], Unnamed Tributary (US of effluent) [8.63], and Powell Slough (DS of effluent) [8.90]

### Results: Lab Analyses

- Sodium results >20 mg/L (EPA Drinking Water Advisory) at most sites
  - Sodium results below 20 mg/L at Butte Creek, Cherokee Canal, and Sutter Bypass
- One Boron result >1 mg/L, but all other sites were below DPH Notification Level for Drinking Water
  - High result in new ditch upstream of effluent pipe in Colusa study area

## Results: Lab Analyses

- Aluminum results >200 μg/L (2<sup>nd</sup> MCL) at most sites
  - Aluminum results <200 μg/L at Lateral #2 DS, Butte Creek, Effluent for Colusa, Live Oak, Willows, and Biggs
- Total Trihalomethane results <80 μg/L</li>
   (MCL) at all sites
  - Bromodichloromethane result > 0.56 μg/L (CTR) at Willows Effluent

# Results: Lab Analyses

- MBAs results < 500 µg/L (2<sup>nd</sup> MCL) at all sites
- Arsenic results < 10 µg/L (MCL) at most sites
  - One Arsenic result > 10 µg/L at Live Oak Effluent
- Manganese results > 50 µg/L (2<sup>nd</sup> MCL) at most sites
  - Manganese results < 50 µg/L at Effluent for Colusa, Live Oak, Willows, and Biggs, Butte Creek



Powell Slough, Upstream of Unnamed tributary. Picture is looking downstream



Ag Drain C at Road 60, before water enters Wildlife Refuge. Looking upstream



Lateral Drain #2, downstream of effluent. Looking upstream



Lateral K, upstream of effluent discharge. Looking downstream

# **Next Monitoring Event**

- Field measurements on May 9 and May 10, 2012
- Key constituents and field measurements week of May 21-25

# Questions?


Data will be available on-line

- Biggs Study Area
  - Butte Creek near Nelson Road
  - Lateral K upstream of effluent
  - ◆ Effluent
  - Lateral K downstream of effluent
  - Cherokee Canal upstream of effluent
  - ◆ C Main Drain upstream of Cherokee Canal
  - Butte Creek in Duck Club/Butte Slough at Meridian

- Colusa Study Area
  - ◆ CBD at Highway 20
  - ◆ Powell Slough at Highway 20
  - ◆ Effluent
  - Unnamed Tributary upstream of effluent
  - New Ditch upstream of effluent
  - Unnamed Tributary downstream of effluent
  - Powell Slough upstream of unnamed tributary
  - Powell Slough downstream of unnamed tributary
  - CBD at Abel Road

- Willows Study Area
  - ◆ Effluent
  - Ag Drain C upstream of effluent
  - Ag Drain C downstream of effluent
  - ◆ Ag Drain C at Road 60
  - ♦ Willow Creek at Road 61
  - ◆ CBD at Road 61
  - Logan Creek downstream of effluent
  - Hunters Creek upstream of effluent

- Willows Study Area
  - ◆ Effluent
  - Ag Drain C upstream of effluent
  - Ag Drain C downstream of effluent
  - ◆ Ag Drain C at Road 60
  - ♦ Willow Creek at Road 61
  - ◆ CBD at Road 61
  - Logan Creek downstream of effluent
  - Hunters Creek upstream of effluent



#### City of Live Oak Wastewater Treatment Plant

